

# ASSET SURVEY

CALNE WITHOUT PARISH COUNCIL

MARCH 2023

## Contents

|                          |    |
|--------------------------|----|
| 1. PEWSHAM WARD.....     | 2  |
| 2. WEST WARD.....        | 4  |
| 3. MIDDLE WARD .....     | 13 |
| 4. EAST WARD .....       | 17 |
| 5. SANDY LANE WARD ..... | 19 |

## 1. PEWSHAM WARD

**Asset:** The Well House

**Location:** A342 Old Derry Hill

**Ward:** Pewsham Ward

**What3Words Location:** originate.serves.treat

**Date of Assessment:** 9<sup>th</sup> March 2023

**Description:**

The structured is a Grade II Listed Building. From the listing description:

Well-house, c1900, circular, 6 timber posts with arched braces carrying conical stone slate roof with ball finial. Circular pennant stone well-head with radiating pennant stone paving around. Top plate with painted inscription 'Here quench your thirst and mark in me an emblem of true charity who while my bounty bestow am neither heard nor seen to flow. Repaid by fresh supplies from heaven for every cup of water given'. Identical to well-houses set up by the Poynder family of Hartham Park at Biddestone, Colerne and Hilmarton, Wilts.



**Condition:** Fair

**Condition notes:**

Significant repairs were undertaken to the Well House in 2002. The Parish Council commissioned Wiltshire Historic Buildings Trusts to undertake a condition survey in 2020. The key findings from that were:

- The structure and stone tile roof remained intact.
- The oak ball finial had split through natural movement.
- Some of the repointing to the stone paving was loose and beginning to break away.
- No items required immediate attention.
- It was recommended to cut back the tree and hedge growth around the building to avoid damage during high winds.

The current condition is similar, although the tree and hedge growth has subsequently been cut back.

The lettering around the inside of the structure is starting to fade in places, as can be seen from the structure.

Part of the foot of one timber post has broken away, as shown in the photograph.

In addition, half of the oak finial has fallen off the apex of the structure and is in storage.

**Recommendations for remedial work (if any):**

It is recommended that the Parish Council arranges for minor repairs to be undertaken to the post footing and finial. This should be arranged in consultation with the Wiltshire Historic Buildings Trust to ensure that it is undertaken sympathetically, and with Wiltshire Council in respect of Listed Building Consent.



## 2. WEST WARD

**Asset:** Studley Noticeboard

**Location:** Studley Lane, Studley

**Ward:** West Ward

**What3Words Location:** dilute.example.abandons

**Date of Assessment:** 27<sup>th</sup> February 2023

**Description:** Parish Council noticeboard.  
(Key Holder: Cllr Robbins.)

**Condition:** Good

**Condition notes:** No issues.

**Recommendations for remedial work (if any):** maintain annual maintenance (clean and re-oil).



**Asset:** Studley Grit Bin

**Location:** Studley Lane, at entrance to Studley Gardens.

**Ward:** West Ward

**What3Words Location:** game.heeding.ruling

**Date of Assessment:** 27<sup>th</sup> February 2023

**Description:** Yellow grit bin, with black lid.

**Condition:** Very Good

**Condition notes:** Installed in November 2021. Bin is full.

**Recommendations for remedial work (if any):** None.



**Asset:** Studley Lane Dog Waste Bin

**Location:** Studley Lane,

**Ward:** West Ward

**What3Words Location:** dilute.example.abandons

**Date of Assessment:** 27<sup>th</sup> February 2023

**Description:** Dog Waste Bin

**Condition:** Installed August 2022

**Condition notes:** Good Condition.

**Recommendations for remedial work (if any):** None.







**Asset:** Dog Waste bin

**Location:** Studley Gardens

**Ward:** West Ward

**What3Words Location:** pursue.driveway.depths

**Date of Assessment:** 27<sup>th</sup> February 2023

**Description:** Dog waste bin (green).

**Condition:** Very Good

**Condition notes:** Installed in 2020, condition excellent.

**Recommendations for remedial work (if any):** none.



**Asset:** Petty Acre Goal Posts

**Location:** Open space off Petty Acre, Derry Hill

**Ward:** West Ward

**What3Words Location:** incurs.losses.ourselves

**Date of Assessment:** 16<sup>th</sup> September 2022

**Description:** Two sets of goal posts on public open space.

**Condition:** Fair

**Condition notes:** Inspected by ROSPA Play Safety on 16<sup>th</sup> September 2022. Minor issues only identified. See separate report.

**Recommendations for remedial work (if any):** No major issues..





**Asset:** Derry Hill Noticeboard

**Location:** Church Road, by entrance to Lansdowne Crescent (west), Derry Hill

**Ward:** West Ward

**What3Words Location:** prouder.leaflet.selects

**Date of Assessment:** 31<sup>st</sup> January 2023

**Description:** Parish Council noticeboard.  
(Key Holder: Cllr Rees.)

**Condition:** Good

**Condition notes:** No issues.



**Recommendations for remedial work (if any):** maintain annual maintenance (clean and re-oil).

**Asset:** Derry Hill Phone Kiosk

**Location:** Church Road, by entrance to Lansdowne Crescent (west), Derry Hill

**Ward:** West Ward

**What3Words Location:** prouder.leaflet.selects

**Date of Assessment:** 31<sup>st</sup> January 2023

**Description:** Redundant red telephone kiosk, now accommodating a Defibrillator installation.

**Condition:** Poor

**Condition notes:** Paintwork is faded and peeling away hinge to the lower part of the door needs replacement



**Recommendations for remedial work (if any):** Full repaint and re glaze required.

**Asset:** Dog Waste Bin

**Location:** Church Road, by eastern entrance to Bowood, Derry Hill

**Ward:** West Ward

**What3Words Location:** explained.factories.outlines

**Date of Assessment:** 31<sup>st</sup> January 2023

**Description:** Green dog waste bin.

**Condition :** Good

**Condition notes:** Lid replaced since the last inspection

**Recommendations for remedial work (if any):** None.



**Asset:** Dog Waste Bin

**Location:** Church Road, opposite the Lansdowne Arms, Derry Hill

**Ward:** West Ward

**What3Words Location:** thickens.pelt.rescue

**Date of Assessment:** 31<sup>st</sup> January 2023

**Description:** Green dog waste bin.

**Condition:** Good

**Condition notes:** lid replaced since last inspection.

**Recommendations for remedial work (if any):** none



**Asset:** Dog Waste Bin

**Location:** Petty Lane, by the Lansdowne Hall, Derry Hill

**Ward:** West Ward

**What3Words Location:** conductor.imprints.furniture

**Date of Assessment:** 31st January 23

**Description:** Green dog waste bin.

**Condition:** Fair

**Condition notes:** Paint on the lid is starting to peel off. Lid still closes.



**Recommendations for remedial work (if any):** Monitor the lid and replace when condition deteriorates.

**Asset:** General Waste Bin

**Location:** Lansdowne Hall, Derry Hill

**Ward:** West Ward

**What3Words Location:** overruns.deed.throat

**Date of Assessment:** 31<sup>st</sup> January 2023

**Description:** Black pole mounted waste bin.

**Condition:** Fair

**Condition notes:** No issues.

**Recommendations for remedial work (if any):** None.



**Asset:** Bench  
**Location:** Tile Court, facing Church Road,  
DerryHill  
**Ward:** West Ward  
**What3Words Location:** diverts.erupts.failed  
**Date of Assessment:** 31<sup>st</sup> January 23



**Description:** Wooden bench  
**Condition:** Good  
**Condition notes:** No issues  
**Recommendations for remedial work (if any):** None.

**Asset:** Bench  
**Location:** Tile Court, facing Lansdowne  
Crescent East, Derry Hill  
**Ward:** West Ward  
**What3Words Location:** slouched.singing.vanilla  
**Date of Assessment:** 31<sup>st</sup> January 2023



**Description:** Wooden bench  
**Condition:** Good  
**Condition notes:** No issues  
**Recommendations for remedial work (if any):** None.



**Asset:** Commemorative stone

**Location:** Lansdowne Hall, Derry Hill

**Ward:** West Ward

**What3Words Location:** suitable.tickling.adapt

**Date of Assessment:** 31<sup>st</sup> January 2023

**Description:** commemorative stone and plaque. Installed June 2022.

**Condition (delete as applicable):** Very Good

**Condition notes:** No issues.

**Recommendations for remedial work (if any):** none required.



### 3. MIDDLE WARD

**Asset:** Stockley Noticeboard

**Location:** Stockley

**Ward:** Middle Ward

**What3Words Location:** something.longingly.incurs

**Date of Assessment:** 23<sup>rd</sup> January 2023

**Description:** Parish Council noticeboard.  
(Key Holder: Cllr Crane.)

**Condition:** Good

**Condition notes:** Glass has been replaced in the last year.



**Recommendations for remedial work (if any):** maintain annual maintenance (clean and re-oil).

**Asset:** Bus Shelter

**Location:** Stockley

**Ward:** Middle Ward

**What3Words Location:** airship.masks.bootleg

**Date of Assessment:** 23<sup>rd</sup> January 2023

**Description:** Bus Shelter (installed 2020)

**Condition:** Very Good

**Condition notes:** Dirty condition



**Recommendations for remedial work (if any):** Needs to be cleaned.

**Asset:** Litter Bin

**Location:** Stockley

**Ward:** Middle Ward

**What3Words Location:** enclosing.forgiving.trim

**Date of Assessment:** 23<sup>rd</sup> January 2023

**Description:** Black litter bin attached to bus stop.

**Condition:** Very Good.

**Condition notes:** No issues.

**Recommendations for remedial work (if any):** None



**Asset:** Stockley Phone Kiosk

**Location:** Stockley

**Ward:** Middle Ward

**What3Words Location:** locate.dubbing.redouble

**Date of Assessment:** 23<sup>rd</sup> January 2023

**Description:** Redundant modern telephone kiosk, now accommodating a Defibrillator installation.

**Condition:** Fair

**Condition notes:** Fundamental condition is good, but cobwebs inside, mould growing on Perspex panels and ivy growing across the floor.



**Recommendations for remedial work (if any):** Would benefit from a clean-up to remove mould, plus removal of ivy from floor and around base.



**Asset:** Stockley Grit Bin  
**Location:** Between Stockley & Broads Green  
**Ward:** Middle Ward  
**What3Words Location:** effort.woven.masts  
**Date of Assessment:** 23<sup>rd</sup> January 2023  
**Description:** Yellow grit bin, with black lid.  
**Condition:** Very Good  
**Condition notes:** Installed in November 2021.  
**Recommendations for remedial work (if any):** None.



**Asset:** Dog Waste Bin  
**Location:** Footpath off The Rise, Cherhill View  
**Ward:** Middle Ward  
**What3Words Location:** relocated.perfect.slimy  
**Date of Assessment:** 3<sup>rd</sup> February 2023  
**Description:** Red dog waste bin.  
**Condition:** Poor.  
**Condition notes:** Lid has been replaced in the last year.



**Recommendations for remedial work (if any):** Bin overflowing, recommend increased collection frequency.

**Asset:** Dog Waste Bin  
**Location:** Morgans Road, Cherhill View  
**Ward:** Middle Ward  
**What3Words Location:** ///roosts.overcomes.product  
**Date of Assessment:** 21<sup>st</sup> February 2023 (installation date)  
**Description:** newly installed, brand new condition  
**Condition:** Very Good.  
**Condition notes:** End cap missing from post  
**Recommendations for remedial work (if any):** Acquire end cap.



**Asset:** Dog waste Bin  
**Location:** Acorn Lane, Cherhill View  
**Ward:** Middle Ward  
**What3Words Location:** ///fiery.requiring.burying  
**Date of Assessment:** 21<sup>st</sup> February 2023 (installation date)  
**Description:** brand new installation.  
**Condition:** Very Good.  
**Condition notes:** No issues.  
**Recommendations for remedial work (if any):** None



## 4. EAST WARD

**Asset:** Lower Compton Notice Board

**Location:** Atcherly Road, Lower Compton

**Ward:** East Ward

**What3Words Location:** exactly.organisms.gazes

**Date of Assessment:** 4<sup>th</sup> February 2023

**Description:** Parish Council Noticeboard  
(Keyholder: Cllr Price)



**Condition:** Good

**Condition notes:** The Perspex is yellowing and need replacing.

**Recommendations for remedial work (if any):** Wood will probably need some treatment in the summer. Perspex needs replacing.

**Asset:** Dog waste bin

**Location:** Atcherly Road, Lower Compton

**Ward:** East Ward

**What3Words Location:** boardroom.packets.broadens

**Date of Assessment:** 4<sup>th</sup> February 2023

**Description:** Red dog waste bin



**Condition:** Good

**Condition notes:** Some flaking paint, and bin overflowing with waste.

**Recommendations for remedial work (if any):** Increase emptying frequency, monitor condition of bin over the next year.

**Asset:** Dog waste bin  
**Location:** Whittle Avenue, Lower Compton  
**Ward:** East Ward  
**What3Words Location:** wakes.blurs.watch  
**Date of Assessment:** 4<sup>th</sup> February 2023  
**Description:** Green dog waste bin.  
**Condition (delete as applicable):** Very Good  
**Condition notes:** No issues.



**Recommendations for remedial work (if any):** increase frequency of emptying to avoid bin overflowing.

**Asset:** Waste bin  
**Location:** Layby off the A4 at Cherhill  
**Ward:** East Ward  
**What3Words Location:** crafts.refrained.tweaked  
**Date of Assessment:** 4<sup>th</sup> February 2023  
**Description:** Black waste bin. Installed Nov 22  
**Condition (delete as applicable):** Very Good  
**Condition notes:** No issues.



**Recommendations for remedial work (if any):** increase frequency of emptying to avoid bin overflowing.



## 5. Sandy Lane

**Asset:** Sandy Lane Noticeboard

**Location:** The George Inn Car Park,

**Ward:** Sandy Lane Ward

**What3Words Location:** twitching.live.tasks

**Date of Assessment:** 25<sup>th</sup> March 2023

**Description:** Noticeboard, installed March 2023

**Condition (delete as applicable):** Very Good

**Condition notes:** No issues. New installation.

**Recommendations for remedial work (if any):** NA

